



Service Light Reset – BMW (1999 to 2001)

Certain instrument clusters require manual reset using buttons on the dashboard. The procedure is as follows:

On cars with no diagnostic socket in the engine compartment, the service interval indicator is reset using left push button in the instrument cluster.

- Ignition key in position "0"
- Press and hold the left button in the instrument cluster
- Turn key to position "1"
- Keep the button pressed, the service status will be displayed after 5 seconds
- The SIA displays OIL SERVICE or INSPECTION and the remaining distance.
- "RESET" is shown if resetting is possible, if no "RESET" is shown the service distance has not been reached and resetting is not possible.
- Keep the button pressed in for a further 5 seconds to enter reset mode
- "RESET" will flash in the display for 5 seconds
- Release, re-pressing and re-releasing the button while "RESET" is flashing

The new distance is displayed for 5 seconds once the resetting procedure has been carried out.