


Audi

Manual Service Reset - Audi A4 and A6 (1995 - 1999)



OM1029

1. With the ignition switch in the OFF position, press and hold button **A** whilst turning the key to the ON position.
2. The message "Service OIL" will appear. If the message does not display, repeat step 1.
3. Pull out the button **B** until the message is extinguished.
4. The display should now show "Service ---", indicating that the SRI has been reset.